Docket No.: 050203-0150 **PATENT**

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of : Customer Number: 31824

Mitsuhiro Nishina, et al. : Confirmation Number: 3412

Application No.: 10/577,222 : Group Art Unit: 3748

Filed: November 28, 2006 : Examiner: Binh Q. Tran

Patent No. 7,467,512

: For: EXHAUST GAS PURIFYING APPARATUS :

AND EXHAUST GAS PURIFYING
METHOD OF AN ENGINE

Commissioner for Patents Office of Patent Publication ATTN: Certificate of Correction Branch P.O. Box 1450 Alexandria, VA 22313-1450

Issued: December 23, 2008

REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322

Sir:

In reviewing the above-identified patent, printing errors were discovered therein requiring correction in order to conform the Official Record in the application.

The errors noted are set forth on the attached copy of form PTO/SB/44 in the manner required by the Commissioner's Notice.

The changes requested herein occurred as a result of printing the Letters Patent and the Certificate should be issued without expense under Rule 322 of the Rules of Practice. Accordingly, Applicants request issuance of the Certificate of Correction.

U.S. Patent No. 7,467,512

Please charge any shortage in fees due in connection with the filing of this paper to Deposit

Account 502203 and please credit any excess fees to such deposit account.

Respectfully submitted,

McDERMOTT WILL & EMERY LLP

Andrew D. Mickelsen Registration No. 50,957

18191 Von Karman Ave., Suite 500 Irvine, CA 92612-7108 Phone: 949.851.0633 ADM:wrj

Facsimile: 949.851.9348

Date: February 10, 2009

ORC 455798-1.050203.0150

Please recognize our Customer No. 31824 as our correspondence address.

U. S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMIG control number.
(Also Form PTD-0165)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO	: 7,467,512	Page1 of1
-----------	-------------	-----------

APPLICATION NO. : 10/577,222

ISSUE DATE : December 23, 2008

INVENTOR(S) : Mitsuhiro NISHINA, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE SPECIFICATION:

Column 4, Line 63: Replace "NO+NO₂.2NH₃ \rightarrow 2N₂+3H₂0" with \rightarrow NO+NO₂+2NH₃ \rightarrow 2N₂+3H₂0-. Column 4, Line 65: Replace "4NH₃+302 \rightarrow 2N₂+6H₂0" with \rightarrow 4NH₃+302 \rightarrow 2N₂+6H₂0-.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

18191 Von Karman Ave., Suite 500

Irvine, CA 92612-7108

This collection of information is required by 37 CFR 1322, 1323, and 1324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO by process) an application. Continentally is governed by 35 US.C. 12 and 37 CFR 1.14 This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/ost suggestions for reducing this butter, should be sent to the Chief Information Office, US. Petent and Trademark Office, US. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1460. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: ATTENTION CERTIficate of Corrections Stranch, Commissioner for Patients, P.O. Box 1450, Alexandria, VA 22313-1450.